DAMS WITH IDENTIFIED SAFETY DEFICIENCIES

Arizona Department of Water Resources
Office of Water Engineering
Dam Safety Section
January 14, 2008

Monday, January 14, 2008

Page 1 of 5

Apache

SID Dam Name	Hazard Class	Nearest Downstream Development	Miles	Safety Deficiencies:
01.28Lee Valley	Significant	Greer	7.00	Lack of Adequate EAP
Cochise				
SID Dam Name	Hazard Class	Nearest Downstream Development	Miles	Safety Deficiencies:
02.02 Parker Canyon	Significant	Los Matates, Mexico	15.00	Lack of Adequate EAP
Coconino				
SID Dam Name	Hazard Class	Nearest Downstream Development	Miles	Safety Deficiencies:
03.02West Cataract Creek	Significant	Williams	2.00	Lack of Adequate EAP
				Outlet Pipe(s) without Upstream Controls
03.04 Santa Fe	High	Williams	0.10	Lack of Adequate EAP
03.10 Dogtown	Significant	Havasupai Indian Reservation & I-40	11.00	Lack of Adequate EAP
				Outlet Pipe(s) without Upstream Controls
Graham				
SID Dam Name	Hazard Class	Nearest Downstream Development	Miles	Safety Deficiencies:
05.04Cluff Ranch #3	Significant	Dublin & Pima	6.00	Lack of Adequate EAP
05.08Riggs Reservoir	Significant	Thatcher	4.00	
301 1	- g			Outlet Pipe(s) without Upstream Controls
05.10Lebanon Reservoir #1 (Upper)	Significant	Safford	13.00	
				Dam StabilityInadequately Abandoned Outlet Pipe
				- madequately Abandoned Odnet Filpe

Monday, January 14, 2008 Page 2 of 5

05.14Judy Wash Retarding	High	Solomon	1.00	Lack of Adequate EAP
05.17 Freeman Wash Retarding	High	Thatcher	1.00	Lack of Adequate EAP Inability to Safely Pass Required Inflow Design Flood
05.21 Roper Lake	High	Safford	5.00	Lack of Adequate EAP Inability to Safely Pass Required Inflow Design Flood
05.28No Name Wash	High	Lone Star	2.00	Lack of Adequate EAP

Greenlee

SID Dam Name	Hazard Class	Nearest Downstream Development	Miles	Safety Deficiencies:
06.07 New Town #2	Significant	U. S. Highway 191	0.50	
				Lack of Engineering Documentation

Maricopa

SID Dam Name	Hazard Class	Nearest Downstream Development	Miles	Safety Deficiencies:
07.21 McMicken	High	Surprise	0.50	Deteriorated or Obstructed Outlet Works Inability to Safely Pass Required Inflow Design Flood Inadequately Abandoned Outlet Pipe
07.24 Gillespie	Significant	Gila Bend	18.00	Partial Breach of Dam
07.28 White Tanks #3	High	Litchfield Park	0.25	Inability to Safely Pass Required Inflow Design Flood
07.29White Tanks #4	High	Goodyear	8.00	 Deteriorated or Obstructed Outlet Works Deteriorated or Obstructed Spillway Embankment Cracking

Monday, January 14, 2008

Page 3 of 5

Monday, January 14, 2008

Page 4 of 5

09.16Lakeside	Significant	Show Low	7.00	 Lack of Adequate EAP
09.18Woodland	High	Pinetop & Lakeside	3.00	• Lack of Adequate EAP

Pima

SID Dam Name	Hazard Class Nearest Downstream	Development Miles Safety Deficiencies:
10.12Arivaca	Significant Arivaca	6.00 • Lack of Adequate EAP

Yavapai

SID Dam Name	Hazard Class	Nearest Downstream Development	Miles	Safety Deficiencies:
13.13 Willow Creek	High	Granite Dells	10.00	Lack of Adequate EAP
13.17Lower Goldwater	High	Prescott	4.00	Lack of Adequate EAP
13.18Upper Goldwater	High	Prescott	4.00	Lack of Adequate EAP
	9			Concrete Deterioration
13.39Little Hell's Canyon	High	US 89	0.00	Lack of Adequate EAP
13.47 Seligman	Significant	Seligman WWTP	0.10	Lack of Adequate EAP
3	3	3		Lack of Engineering Documentation
13.52Zonia Southwest Holding Tank	Low	Kirkland Junction	6.00	Lack of Adequate EAP
				Lack of Engineering Documentation
13.55 Scissor Tank	Significant	Utility building	1.50	
				Lack of Engineering Documentation

Monday, January 14, 2008

Page 5 of 5